

# PRODUCT ANNOUNCEMENT

KENNEDY TECHNOLOGY GROUP  
RELEASE DATE: 2/27/09 - Document #65430R0

This announcement contains release information on seven (7) new harnesses.

Description: These 5 pin DIN harnesses can be used to replace broken or worn-out Honda OEM harness installed on Goldwing 1500's, 1800's, or Valkyries (use 1800). An unterminated version is also available for customer selected termination.

They offer a weather boot with protective cover.

More information on this harness can be found at <http://www.cellset.com/5pinDINpigtail.html>

Description	Length	Part Number	Cost (USD)
1500 Intercom	2 ft	95504	20
1500 Intercom	4 ft	95505	20
1500 Intercom	6 ft	95506	20
1800 Intercom	2 ft	95507	20
1800 Intercom	4 ft	95508	20
1800 Intercom	6 ft	95509	20
Unterminated	6 ft	95510	15