

# PRODUCT RELEASE ANNOUNCEMENT

KENNEDY TECHNOLOGY GROUP

RELEASE DATE: 09/06/07 - Part #65348R0

Market: GL1500 Motorcycles.

Product: *Auxiliary audio retrofit service*

Part #: varies. see below

MSRP: USD99.99

Description: This retrofit service adds a switching circuit and an auxiliary audio input connector to OEM GL1500 audio units.

Two version are available:

1. Connect the audio unit directly to any stereo source that has a 3.5mm stereo connector. Order part number 95448.
2. Connect to Kennedy ground loop isolators and audio switchers. Order part number 95449.

The design also includes a connector that allows the user to connect a switch to the retrofit circuit to route the audio source back and forth between the external source and the internal AM/FM radio. Any Kennedy GPS simple switch assembly (round, square or toggle) or relay timer assembly can be used. Any one of the Kennedy simple switch assemblies is included in the cost, shown above. There is an additional charge of \$40 should the customer elect to employ the Kennedy relay timer switch assembly.

When used in conjunction with a Kennedy CellSet, MC/GPS3 or MC/GPS-Aux/ICS, a special splitter cable is required. This harness allows a single, simple switch or relay timer assembly to control both the Kennedy MC/GPS and the retrofit circuitry. This harness part number is 95450. The price is USD15.00

External sources which are powered from the motorcycle may require a ground loop isolator (e.g., Kennedy IsoSet2).

Please note that the cost for this retrofit is nonrefundable and that the service may void any warranty in effect at the time of its installation.

Call for a return authorization number (RMA) and shipping instructions. Do not send units to the Kennedy, Rose Hill, Kansas, facility.

If audio units are found to be defective upon receipt, they will be returned unopened, freight collect.

More information can be found at: <http://www.cellset.com/retrofit>