


A B C D E F G H J K L M N P



J1 Reference

Pin	Signal
1	Mic Hi
2	Mic Lo
3	Radio Out Hi
4	Radio Out Lo
5	PTT Hi
6	PTT Lo



NOTES:  
 1. DO NOT CRIMP TINNED WIRE  
 2. CRIMP THE BRAID WIRE WITH TERMINAL 40118

To key radio: Connect PTT Hi to radio gnd via 27k resistor



separately cap the blue, yellow, and green wires with 3/64"dia x 1/4" heat shrin

THIS DRAWING IS THE PROPERTY OF THE KENNEDY TECHNOLOGY GROUP, ROSE HILL, KANSAS			
<b>Kennedy Technology</b>		UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN INCHES TOLERANCES: LINEAR Fractional - 1/32" 0.015 ± 0.15 0.005 ± 0.015 0.000 ± 0.0015 ANGULAR ± 0.5 DEG.	
REFERENCE	85539	RADIO HARNESS ASSY, FT90	
SIZE	B	DWG NO. 95275	REV. NO. 1
SCALE: NONE		FOR ASSISTANCE CONTACT: vox 316-776-1111 fax 316-776-9035	DRAWN _____ DATE _____
SHEET 1 OF 1		CHECKED _____	DATE _____

A B C D E F G H J K L M N P